

Crocker Farm Elementary School

	Fixture	Sample Type	Initial Testing			Repair/Replacement		Resample Testing			
			Date	Lead Results		Action Taken	Date	Action Taken	Date	Lead Results	
Room 202	Bubbler	First Draw	8/3/2016	3.7	ppb	Turned off			9/29/2016	3.2	ppb
Room 202	Faucet	First Draw	8/3/2016	19	ppb	Turned off			9/29/2016	1.6	ppb
Room 202	Faucet	Flush	8/3/2016	1.3	ppb	Turned off			9/29/2016	1.1	ppb
Room 24	Bubbler	First Draw	8/3/2016	170	ppb	Turned off			9/29/2016	22	ppb
Room 24	Faucet	First Draw	8/3/2016	38	ppb	Turned off			9/29/2016	37	ppb
Room 24	Faucet	Flush	8/3/2016	7.1	ppb	Turned off			9/29/2016	5.5	ppb
Room 26	Bubbler	First Draw	8/3/2016	3.8	ppb	Turned off			Fixture below AL, not retested.		
Room 26	Faucet	First Draw	8/3/2016	17	ppb	Turned off			9/29/2016	4	ppb
Room 26	Faucet	Flush	8/3/2016	1.7	ppb	Turned off			9/29/2016	1.8	ppb
Room 30	Bubbler	First Draw	8/3/2016	13	ppb	Turned off			9/29/2016	62	ppb
Room 30	Faucet	First Draw	8/3/2016	32	ppb	Turned off			9/29/2016	4	ppb
Room 30	Faucet	Flush	8/3/2016	2.2	ppb	Turned off			9/29/2016	1.7	ppb